

Audi



VIN: WAUZZZF33M1146618

Generat pe 23.02.2025, 17:34



Odometru

✓ Arată bine



Statut legal

✓ Arată bine



Daune

✓ Arată bine



+31

Surse de date

Am verificat 900+ de surse de date în 35 de țări

Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?



Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



Notă

Am încheiat verificarea bazelor de date ale poliției privind vehiculele furate din 8 țări:  +2

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nicio înregistrare



Furat în trecut

✓ Nu s-a găsit nicio înregistrare

Starea actuală necunoscută



Furat în trecut

✓ Nu s-a găsit nicio înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**



România



Danemarca



Statele Unite ale Americii



Lituania



Slovacia



Suedia



Slovenia



Cehia


Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?



Notă

- Ultimul kilometraj cunoscut: 60.984 km
- 2 înregistrări ale kilometrajului



2023

2024

Înregistrările odometrului

01.2023 32.068 km

05.2024 60.984 km

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?



Nu s-au găsit probleme

Nu s-au găsit înregistrări despre statutul legal al acestui vehicul

Legal



Inspecție tehnică periodică (ITP)

✓ Nu s-a găsit nicio înregistrare

Nu au fost găsite înregistrări ale inspecției tehnice



Casat

✓ Nu s-a găsit nicio înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

✓ Nu s-au găsit probleme

Înregistrări de daune



Ocazional pot apărea inexactități, mai ales la verificarea vehiculelor vechi. Atelierele clandestine de reparații pot deghiza ilegal defectele sau daunele vehiculelor, fără să declare nicăieri existența lor. Uneori până și plăcuțele VIN ale vehiculului pot fi înlocuite. Avem o varietate de metode de a detecta chiar și astfel de infracțiuni, dar este imposibil de oferit o garanție de 100%.

Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

✓ Nu s-au găsit probleme

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

i Notă

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător
Audi



Tip caroserie
SUV



Capacitate cilindrică
1,5 l



Putere motor
118 kW (158 cp)



Cutie de viteze
Automată



Tip transmisie
Tracțiune față (FWD)



Amplasarea volanului
Volan pe stânga



Cod motor
DFYA

Echipare

Cum a fost primit de la producător

0AL FRONT STABILIZER	0B3 WHEELBASE
0BG REAR STABILIZER	0FA STANDARD MANUFACTURING SEQUENCE
0IJ INSTALLATION DIFFERENTIATION FOR TRANSMISSION "DQ381" -- VEHICLE COMPONENTS --	0K4 HYBRID PROPULSION SYSTEM I-HEV
0LU WITH SPECIAL PLATES/LABELS/ SAFETY CERTIFICATES FOR BELGIUM	0P0 REAR EXHAUST TAILPIPE (STANDARD)
0RE WITHOUT ELECTRONIC STEERING COLUMN LOCK	0SS LABELS/PLATES IN ENGLISH AND FRENCH
0TD FLOOR MATS IN FRONT AND REAR	0XN INFORMATION KIT IN FRENCH AND DUTCH
0Y1 STANDARD CLIMATIC ZONES	0YN WEIGHT RANGE 13 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST
1A5 FUEL SYSTEM FOR SI ENGINE	1AE BRS FOR VEHICLES WITH ELECTRIC DRIVE (ESC AND ELECTRIC BRAKE BOOSTER)
1E5 ACTIVATED CARBON CANISTER FOR INTENSIFIED EVAPORATION SYSTEM WITH ON-BOARD DIAGNOSTIC SYSTEM 2	1EX SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1G8

BREAKDOWN KIT

1M6

TRAILER HITCH MECHANICALLY SWIVELING
ANDPOWER-DETACHABLE

1NL

TRIMS FOR ALLOY WHEELS

1S3

TOOL KIT

1T3

FIRST AID KIT WITH WARNING TRIANGLE

1U8

WITHOUT FOLDING TABLE ON FRONT SEAT
BACKREST

1X0

FRONT WHEEL DRIVE

1Z1

INCREASE IN INITIAL STANDARD FUEL FILLING

20A

WITHOUT ELECTRIC MOTOR (HYBRID)

2H0

WITHOUT "DRIVE SELECT"

2P2

STAINLESS STEEL LOADING EDGE PROTECTION

2Z8

TYPE SIGN AND COMPANY LOGO

3B4

CHILD SEAT ANCHOR FOR CHILD SEAT SYSTEM
ISOFIX

3FA

WITHOUT ROOF INSERT (STANDARD ROOF)

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3M0

WITHOUT SPECIAL MEASURES

3T2

THREE REAR HEAD RESTRAINTS

4A3

1JC

REAR SHOCK ABSORPTION FOR SPORTS VERSION

1N3

SPEED-RELATED VARIABLE STEERING ASSIST
(SERVOTRONIC)

1PA

STANDARD WHEEL BOLTS

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1TS

VEHICLE CLASS DIFFERENTIATION F30-

1VG

INSTALLATION PARTS FOR FOUR-CYLINDER ENGINE

1XW

LEATHER-WRAPPED MULTIFUNCTION SPORTS
STEERING WHEEL

1ZK

DISK BRAKES IN FRONT

2EM

DISK BRAKES IN REAR

2JD

SPORTS BUMPERS

2WA

WITHOUT ADDITIONAL TIRES

31B

REAR LICENSE PLATE CARRIER (ECE)

3CA

WITHOUT PARTITION

3G0

WITHOUT CHILD SEAT ANCHOR FRONT (ISOFIX)

3L3

MANUAL HEIGHT ADJUSTMENT FOR FRONT SEATS

3S2

BLACK ROOF RAILS

3ZU

3-POINT SEAT BELTS, OUTER REAR WITH ECE LABEL

4D0

SEAT HEATER FOR FRONT SEATS SEPARATELY
CONTROLLED

4E7

TAILGATE/TRUNK LID POWER CLOSING

4H3

MANUAL CHILD SAFETY LOCK

4L6

BREAKAWAY INTERIOR REARVIEW MIRROR, AUTO-
DIMMING

4X3

SIDE AIRBAG IN FRONT, WITH CURTAIN AIRBAG

5C0

WITHOUT SPECIAL BODY MEASURES

5J1

REAR SPOILER

5KR

REAR SEAT BENCH/BACKREST, SPLIT FOLDING

5MA

DECORATIVE INSERTS

5SL

LEFT EXTERIOR MIRROR: ASPHERICAL

6A0

WITHOUT FIRE EXTINGUISHER

6F4

SIDE DECORATIVE FILMS

6K2

FORWARD COLLISION WARNING INCL. AUTONOMOUS
EMERGENCY BRAKING, WITHOUT ADAPTIVE CRUISE
CONTROL

6XE

EXTERIOR MIRRORS, POWER-FOLDING AND POWER-
ADJUSTABLE/HEATED

73A

WITHOUT CHARGING CABLE (INDUSTRIAL
CONNECTOR)

7AA

ELECTRONIC ENGINE IMMOBILIZER

WITHOUT SEAT VENTILATION/MASSAGE SEAT

4GF

WINDSHIELD IN HEAT-INSULATING GLASS

4I3

CENTRAL LOCKING SYSTEM "KEYLESS ENTRY"
WITHOUT SAFELOCK

4UF

DRIVER AND FRONT PASSENGER AIRBAG WITH
FRONT PASSENGER AIRBAG DEACTIVATION

4ZE

BLACK MOLDINGS

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5K5

TRANSIT COATING FILM WITH ADDITIONAL
TRANSPORT PROTECTION MEASURES

5L0

WITHOUT FRONT SPOILER

5RU

RIGHT EXTERIOR MIRROR: CONVEX (LARGE VIEWING
FIELD)

5ZF

FRONT HEAD RESTRAINTS

6E3

CENTER ARMREST IN FRONT

6FA

COMPONENTS WITHOUT SPECIAL SURFACE
APPEARANCE

6NJ

STANDARD MOLDED HEADLINER

6Y2

SPEED LIMITER

76A

WITHOUT MODE 3 CHARGING CABLE

7B0

WITHOUT SOCKET

7E0

WITHOUT HEAT ACCUMULATOR/AUXILIARY HEATER

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7P0

WITHOUT LUMBAR SUPPORT IN SEAT BACKRESTS

7W1

WITH EXTENDED SAFETY SYSTEM (PROACTIVE PASSENGER PROTECTION SYSTEM)

7Y5

LANE CHANGE ASSIST AND LANE KEEPING SYSTEM

8G0

WITHOUT LIGHT CONTROL

8K4

SEPARATE DAYTIME RUNNING LIGHTS -- NAR --

8Q3

AUTOMATIC HEADLIGHT RANGE ADJUSTMENT DYNAMIC (SELF-ADJUSTING WHILE DRIVING)

8T6

CRUISE CONTROL SYSTEM AND SPEED LIMITER

8W1

WASHER FLUID LEVEL INDICATOR

8X0

WITHOUT HEADLAMP WASHER SYSTEM

8Z5

NOT HOT COUNTRY

9G8

BELT-DRIVEN STARTER ALTERNATOR 48 V 110-250 A

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9WC

WITHOUT "MULTIMEDIA" IN VEHICLE

9ZV

COMFORT TELEPHONY, WITHOUT ANTENNA CONNECTION

A51

AUDI AG

7HC

LEATHER VARIANT 2

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7UG

NAVIGATION SYSTEM - HIGH

7X2

PARK DISTANCE CONTROL IN FRONT AND REAR

8FA

WITHOUT SECOND BATTERY

8IT

LED HEADLAMPS

8N6

WINDSHIELD WIPER INTERMITTENT CONTROL WITH LIGHT/RAIN SENSOR

8RL

6 SPEAKERS (PASSIVE)

8TB

REAR FOG LAMP

8WA

WITHOUT FRONT FOG LAMPS

8Y1

TWO-TONE HORN

9AK

CLIMATRONIC WITH IMPACT PRESSURE CONTROL, CFC-FREE

9JA

NON-SMOKER'S PACKAGE

9S9

.

9Z0

OPERATING VOLTAGE 12 V

A00

NO SELF-COLLECTION

A8Y

OFF-ROAD

AQ0

STANDARD-PRODUCTION QUALITY

B02

TYPE APPROVAL COUNTRY BELGIUM

C26

OPERATING PERMIT, ALTERATION

D8I

4-CYLINDER SI ENGINE 1.5 L/118 KW MILD HYBRID, TSI
MV BASE ENGINE IS TJ7

EB4

1 YEAR FOLLOW-ON WARRANTY, MAX. 120 000 KM

EL5

ONLINE SERVICE, WITH OCU, WITH HEAD
UNITCODING, WITHOUT ENGINE IMMOBILIZER
INTERCONNECTION

EV0

WITHOUT CHARGING CABLE

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD
EQUIPMENT

FM0

BASIC EQUIPMENT VARIANT

FZ1

N.N.N. TYPE 1

G1C

SEVEN-SPEED AUTOMATIC TRANSMISSION

GM1

STANDARD ELECTRONIC ENGINE SOUND

GT6

PLASTIC DECORATIVE INSERTS, HIGH GLOSS

IX1

SI ENGINE

J94

SUSPENSION RANGE 94

KA6

WITH FRONT AND REAR VIEW CAMERA SYSTEM AND
TWO SIDE CAMERAS

L0L

LEFT-HAND DRIVE

AV1

DRIVING ON THE RIGHT

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-
SPECIFIC BUILDING REGULATION

C3Q

ALLOY WHEELS 7J X 18

E0A

NO SPECIAL EDITION

EF0

WITHOUT ECO FUNCTION

ER1

REGIONAL CODE " ECE " FOR RADIO

EW0

WITHOUT MAINTENANCE CONTRACT

FA0

CONTROL OF SERIES PRODUCTION

FQ0

PRODUCTION WHEELS

G03

SHOCK ABSORPTION IN FRONT

GB0

WITHOUT BOOSTER

GP0

VEHICLES WITHOUT SPECIAL UPGRADE MEASURES

IT4

WITH CONNECT PACKAGE 4

J0V

BATTERY 420 A (70 AH)

K4H

CLOSED BODY

KK3

REFRIGERANT R1234YF

L18

N1M

SEAT TRIM COVERS IN PART LEATHER

NT0

TRANSIT COATING (TYPE 1)

Q1A

STANDARD SEATS IN FRONT

QG1

SERVICE INTERVAL PROLONGATION

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS (VARIABLE)

QK1

WITH MULTIFUNCTION CAMERA

QQ1

WITH ADDITIONAL LIGHTS (INTERIOR LIGHTING)

QV3

DIGITAL RADIO RECEPTION

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

UH2

PARKING BRAKE

UK1

STANDARD REAR SEAT RELEASE

VC0

WITHOUT REMOTE-CONTROLLED GARAGE DOOR OPENER

VT5

SCUFF PLATES IN DOOR APERTURES

SUSPENSION RANGE 18 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

NM1

ENGINE COVER

NZ4

PRIVATE EMERGENCY CALL SYSTEM

QE0

WITHOUT STORAGE COMPARTMENT PACKAGE/BOX

QH1

VOICE CONTROL

QJ0

WITHOUT ALUMINUM/CHROME PACKAGE

QL5

DARK TINTED GLASS IN REAR SEAT AREA (VENUS 35/PRIVACY) HEAT-INSULATING GLASS (GREEN) IN FRONT

QR9

WITH DYNAMIC ROAD SIGN DISPLAY

TJ7

4-CYLINDER SI ENGINE 1.5 L UNIT 05E.A

UG1

HILL START ASSIST

UI2

ELECTRIC INTERFACE FOR EXTERNAL USE AUX-IN JACK AND 2 X USB

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

VF0

STANDARD PEDAL CLUSTER

X2A

EQUIPMENT OPTIONS SUBSET FOR BELGIUM



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**