

Seat formmentor



VIN: VSSZZZKM*****

Benzină

Generat pe 20.02.2025, 21:45



Odometru

✓ Arată bine



Statut legal

✓ Arată bine



Daune

✓ Arată bine



+31

Surse de date

Am verificat 900+ de surse de date în 35 de țări

Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?



Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în 9 țări:



+3

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**



România



Statele Unite ale Americii



Slovacia



Danemarca



Lituania



Slovenia



Suedia



Italia



Cehia


Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?



Notă

- Ultimul kilometraj cunoscut: 10 km
- 1 înregistrare a kilometrajului



2021

Înregistrările odometrelui

02.2021

10 km

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?



Nu s-au găsit probleme

Nu s-au găsit înregistrări despre statutul legal al acestui vehicul

Legal



Inspecție tehnică periodică (ITP)

✓ Nu s-a găsit nici o înregistrare

Nu au fost găsite înregistrări ale inspecției tehnice



Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?



Nu s-au găsit probleme

Înregistrări de daune



Ocazional pot apărea inexactități, mai ales la verificarea vehiculelor vechi. Atelierele clandestine de reparații pot deghiza ilegal defectele sau daunele vehiculelor, fără să declare nicăieri existența lor. Uneori până și plăcuțele VIN ale vehiculului pot fi înlocuite. Avem o varietate de metode de a detecta chiar și astfel de infracțiuni, dar este imposibil de oferit o garanție de 100%.

Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

- ✓ Nu s-au găsit probleme
Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Emisii

Câte emisii de CO2 produc vehiculele din acest model/an?

- i Notă
Emisii CO2: E (175 g/km)

Emisii CO₂

Emisiile CO2 ale
vehiculului tău
175 g/km Clasă **E**



Emisii CO₂ g/km

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?



Notă

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător

Seat



Model

formentor



Descriere

Formentor



Tip caroserie

Break



Capacitate cilindrică

2 l



Putere motor

228 kW (306 cp)



Tip combustibil

Benzină



Cutie de viteze

Automată



Amplasarea volanului

Volan pe stânga



Nr. locuri

5



Emisii CO₂

175 g/km

Echipare

Cum a fost primit de la producător

05Z

WITHOUT SPECIAL SPECIFICATIONS

0B3

WHEELBASE

0F1

0AF

FRONT STABILIZER

0BE

REAR STABILIZER

0FA

FUEL SYSTEM FOR SI ENGINE, ETHANOL FUEL

0IJ

INSTALLATION DIFFERENTIATION FOR TRANSMISSION "DQ381" -- VEHICLE COMPONENTS --

0N4

4-LINK REAR SUSPENSION

0TA

WITHOUT FLOOR MATS

0Y1

STANDARD CLIMATIC ZONES

1AQ

BRS FOR VEHICLES WITHOUT ELECTRIC DRIVE (ESC AND ELECTRIC BRAKE BOOSTER)

1E5

ACTIVATED CARBON CANISTER FOR INTENSIFIED EVAPORATION SYSTEM WITH ON-BOARD DIAGNOSTIC SYSTEM 2

1G8

BREAKDOWN KIT

1KY

DISK BRAKES IN REAR

1PE

WHEEL BOLTS WITH ANTI-THEFT PROTECTION (UNLOCKABLE)

1S3

TOOL KIT

1T0

WITHOUT FIRST AID KIT AND WARNING TRIANGLE

1Y3

ELECTRONIC DIFFERENTIAL LOCK XDS DYNAMIC TRACTION CONTROL

20A

WITHOUT ELECTRIC MOTOR (HYBRID)

2F0

WITHOUT LOCKING AND STARTING SYSTEMS

2JQ

SPORTS BUMPERS

STANDARD MANUFACTURING SEQUENCE

0K0

WITHOUT ALTERNATIVE DRIVE SYSTEM

0NA

WITHOUT NAMEPLATE SET (WITHOUT MODEL DESIGNATION)

0VG

INFORMATION KIT IN ITALIAN

0YG

WEIGHT RANGE 7 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1D0

WITHOUT TRAILER HITCH

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1J2

SOUND DEADENING PACKAGE AND ADDITIONAL ENCLOSURES FOR SOME UNITS

1LE

DISK BRAKES IN FRONT

1Q0

WITHOUT MASS DAMPER FOR STEERING WHEEL

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1X1

FOUR WHEEL DRIVE

1Z0

INITIAL STANDARD FUEL FILLING

2A0

WITHOUT DELIVERY EQUIPMENT

2I0

ADAPTIVE CHASSIS CONTROL WITH CONTINUOUS OPERATION

2KY

2PZ

LEATHER-WRAPPED STEERING WHEEL FOR AIRBAG SYSTEM (REST-OF-THE-WORLD) (LIGHTWEIGHT DESIGN)

2Z3

TYPE SIGN AND COMPANY LOGO

3C7

3-POINT SEAT BELT FOR CENTER REAR SEAT

3FU

BIG ROOF SYSTEM

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3LW

PART-LEATHER DOOR AND SIDE TRIM PANEL

3PH

POWER SEAT ADJUSTMENT WITH MEMORY FEATURE FOR LEFT SEAT, RIGHT SEAT MANUALLY HEIGHT-ADJUSTABLE

3S5

BLACK ROOF RAILS

3W0

WITHOUT ADDITIONAL NOISE SUPPRESSION MEASURES FOR PASSENGER COMPARTMENT

40S

ALLOY WHEELS 8J X 19

4B1

PROTECTIVE SIDE MOLDING

4E6

SENSOR-CONTROLLED LUGGAGE COMPARTMENT OPENER

4GW

HEAT INSULATING WINDSHIELD

4KF

SIDE WINDOWS IN HEAT-INSULATING GLASS, FROM B-PILLAR AND REAR WINDOW DARK TINTED

4P0

LABELS/PLATES IN ITALIAN, SPANISH AND PORTUGUESE

2WA

WITHOUT ADDITIONAL TIRES

31F

FRONT LICENSE PLATE CARRIER (LARGE)

3CA

WITHOUT PARTITION

3GN

VARIABLE CARGO AREA

3J9

HEAD RESTRAINT FOR FRONT SEAT

3NU

REAR SEAT BENCH UNSPLIT, BACKREST SPLIT FOLDING WITH CENTER ARMREST

3QC

3-POINT SEAT BELTS IN FRONT

3T2

THREE REAR HEAD RESTRAINTS

3ZU

3-POINT SEAT BELTS, OUTER REAR WITH ECE LABEL

4A3

SEAT HEATER FOR FRONT SEATS SEPARATELY CONTROLLED

4D0

WITHOUT SEAT VENTILATION/MASSAGE SEAT

4G3

STORAGE COMPARTMENT, LEFT AND RIGHT 1ST ROW OF SEATS

4K6

CENTRAL LOCKING SYSTEM "KEYLESS ENTRY" WITH FINGERPRINT "TWO-STAGE UNLOCKING"

4L6

BREAKAWAY INTERIOR REARVIEW MIRROR, AUTO-DIMMING

4R4

REAR FLOOR PANEL MODULE, TYPE 1

4U5

LUGGAGE POCKETS ON BACKREST

4ZD

BLACK MOLDINGS

5C0

WITHOUT SPECIAL BODY MEASURES

5J1

REAR SPOILER

5K4

TRANSPORT PROTECTION COVER (SHAPE- ADAPTED SYSTEM) WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5XJ

SUN VISORS WITH MIRROR, ILLUMINATED, WITH AIRBAG LABEL ON SUN VISOR AND B-PILLAR

6C2

SIDE AIRBAG IN FRONT WITH CURTAIN AIRBAGAND INTERACTION AIRBAG IN FRONT

6F3

EMBLEMS

6I6

LANE KEEPING SYSTEM PLUS SEMI-AUTOMATIC VEHICLE CONTROL IN A MEDICAL EMERGENCY AND TRAFFIC JAM ASSIST

6Q0

WITHOUT GEARSHIFT KNOB/HANDLE

76A

WITHOUT MODE 3 CHARGING CABLE

7AL

ANTI-THEFT ALARM SYSTEM, INTERIOR MONITORING, BACKUP HORN, AND TOWING PROTECTION

7E0

WITHOUT HEAT ACCUMULATOR/AUXILIARY HEATER

7K1

POWER WINDOWS WITH COMFORT OPERATION ANDCIRCUIT BREAKER

4UF

DRIVER AND FRONT PASSENGER AIRBAG WITH FRONT PASSENGER AIRBAG DEACTIVATION

5A5

LUGGAGE COMPARTMENT LINING, WITH STORAGECOMPARTMENTS

5F1

1 ARMREST FOR LEFT FRONT SEAT AND 2 ARMRESTS FOR RIGHT FRONT SEAT

5JB

AMBULANCE SEAT FOR MEDICAL STAFF WITH HEAD BOLSTER ON PARTITION

5MA

DECORATIVE INSERTS

6A0

WITHOUT FIRE EXTINGUISHER

6E3

CENTER ARMREST IN FRONT

6FH

EXTERIOR MIRROR HOUSINGS PAINTED

6NL

UNSPLIT MOLDED HEADLINER

6XQ

EXTERIOR MIRRORS: WITH MEMORY FEATURE, POWER-FOLDING/ADJUSTABLE, SEPARATELY HEATED

77G

DATA STORAGE DEVICE FOR EU, INTEGRATED

7B0

WITHOUT SOCKET

7G0

WITHOUT PREPARATION FOR VTS (VEHICLE TRACKING SYSTEM)

7L6

DIRECT TIRE PRESSURE MONITORING SYSTEM

7P7

POWER-ADJUSTABLE LUMBAR SUPPORT FOR
LEFTFRONT SEAT

7W0

WITHOUT EXTENDED SAFETY SYSTEM

8AW

CHINA DVD RADIO

8G1

HIGH-BEAM CONTROL

8IY

LED HEADLAMPS WITH LENS

8M1

REAR WINDOW WIPER AND WASHER SYSTEM WITH
INTERMITTENT CONTROL

8Q3

AUTOMATIC HEADLIGHT RANGE ADJUSTMENT
DYNAMIC (SELF-ADJUSTING WHILE DRIVING)

8T8

ADAPTIVE CRUISE CONTROL (WITH "FOLLOW-TO-
STOP") AND SPEED LIMITER

8W1

WASHER FLUID LEVEL INDICATOR

8X6

WITHOUT HEADLAMP WASHER SYSTEM, WITHOUT
WASHER FLUID LEVEL INDICATOR

8Z5

NOT HOT COUNTRY

9I5

SEPARATE DAYTIME RUNNING LIGHTS WITH
AUTOMATIC HEADLAMP ACTIVATION AND COMING
HOME FEATURE (AUTOMATIC)

9JA

NON-SMOKER'S PACKAGE

9P4

SEAT BELT REMINDER, ELECTRIC CONTACT IN FRONT
AND REAR, VISUAL AND ACOUSTICAL

9VG

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7UG

NAVIGATION SYSTEM - HIGH

7X5

PARK ASSIST

8FA

WITHOUT SECOND BATTERY

8GU

ALTERNATOR 140 A

8J3

HAND BRAKE/LOW BRAKE FLUID LEVEL
WARNINGLIGHT AND INSCRIPTION

8N6

WINDSHIELD WIPER INTERMITTENT CONTROL WITH
LIGHT/RAIN SENSOR

8S4

TWO READING LIGHTS IN FRONT, TWO IN REAR

8TB

REAR FOG LAMP

8WB

FRONT FOG LAMPS

8Y1

TWO-TONE HORN

8ZQ

ANTENNA FOR FM RECEPTION ONLY, DIVERSITY

9IJ

COMFORT TELEPHONY WITH LTE AND WIRELESS
CHARGING

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING
HEATER

9T0

WITHOUT HEATED WASHER NOZZLES

9WY

SOUND SYSTEM WITH SUBWOOFER "BRANDED"
DESIGN 2

9Z3

12-V OPERATING VOLTAGE AND 230-V INVERTER

AV1

DRIVING ON THE RIGHT

B14

TYPE APPROVAL COUNTRY ITALY (SAN MARINO,
VATICAN CITY)

D02

4-CYLINDER SI ENGINE 2.0 L/228 KW TFSI,
HOMOGENEOUS BASE ENGINE IS TT6

EA0

WITHOUT FOLLOW-ON WARRANTY

EM1

DRIVER ALERT SYSTEM

ES0

WITHOUT VEHICLE INLET

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD
EQUIPMENT

FC0

WITHOUT CUSTOMIZED INSTALLATION

G04

SHOCK ABSORPTION IN FRONT

GB1

BOOSTER TYPE 1

GP0

VEHICLES WITHOUT SPECIAL UPGRADE MEASURES

J0V

BATTERY 420 A (70 AH)

KA2

WITH REAR VIEW CAMERA SYSTEM (TYPE 2)

KK3

REFRIGERANT R1234YF

MIRROR LINK AND WIRELESS "APP" AND RSE
(PREPARATION)

A8I

SPORTS EQUIPMENT

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-
SPECIFIC BUILDING REGULATION

C02

OPERATING PERMIT, ALTERATION

E0A

NO SPECIAL EDITION

EL5

ONLINE SERVICE, WITH OCU, WITH HEAD
UNITCODING, WITHOUT ENGINE IMMOBILIZER
INTERCONNECTION

ER1

REGIONAL CODE " ECE " FOR RADIO

EVO

WITHOUT CHARGING CABLE

FA0

CONTROL OF SERIES PRODUCTION

FM0

BASIC EQUIPMENT VARIANT

G1D

7-SPEED AUTOMATIC TRANSMISSION FOR FOUR-
WHEEL DRIVE

GM1

STANDARD ELECTRONIC ENGINE SOUND

GW0

WITHOUT CAR2X

K8P

MPV

KH7

CLIMATRONIC (3-ZONE) WITH REAR AIR
CONDITIONING CONTROL PANEL

KS0

WITHOUT HEAD-UP DISPLAY

L0L

LEFT-HAND DRIVE

N5W

SEAT TRIM COVERS IN LEATHER

Q1D

SPORTS SEATS IN FRONT

Q9B

DECORATIVE INSERTS FOR CONSOLE

QH1

VOICE CONTROL

QJ1

CHROME PACKAGE

QN2

DRAWER UNDER RIGHT FRONT SEAT

QR9

WITH DYNAMIC ROAD SIGN DISPLAY

QZ0

SPEED-RELATED VARIABLE STEERING ASSIST
(SERVOTRONIC) W/ REDUCED STEERING HEIGHT

SZ6

CONTROL NUMBER

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

UB1

REAR SHOCK ABSORPTION FOR SPORTS VERSION

UK3

MECHANICAL REAR SEAT RELEASE

VF1

PEDAL CLUSTER

VT2

SCUFF PLATES IN DOOR APERTURES (ILLUMINATED)

L11

SUSPENSION RANGE 11 INSTALLATION CONTROL
ONLY, NO REQUIREMENT FORECAST

NZ4

PRIVATE EMERGENCY CALL SYSTEM

Q48

TIRES 245/40 R19 94W (POLYMER COATING)

QG1

SERVICE INTERVAL PROLONGATION

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS (VARIABLE)

QK1

WITH MULTIFUNCTION CAMERA

QQ9

INTERIOR AMBIENT LIGHTING, TYPE 2

QV3

DIGITAL RADIO RECEPTION

SD9

SPECIAL PRICE

T3W

4-CYLINDER SI ENGINE 1.3 L UNIT 030.2

U9C

2 X USB TYPE C

UH2

PARKING BRAKE

VOA

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

VH0

STANDARD ELECTRIC

X4C

EQUIPMENT OPTIONS SUBSET FOR ITALY

Cronologie

S-au găsit 4 înregistrări

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

02.2021  Italia



Proprietarul s-a schimbat

Țara (sau statul) a indicat locația geografică a unei schimbări sau reînnoiri documentate de proprietar. Vă rugăm să rețineți că unele modificări pot fi formale, de exemplu, transferurile de la sfârșitul contractului de leasing sau situații similare.

02.2021  Italia



A fost la vânzare

Această înregistrare a fost creată deoarece vehiculul a fost listat pentru vânzare pe o anumită piață. Uneori, țara (sau statul) vânzătorului suprascrie locația reală a vehiculului.

02.2021  Italia



A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

07.2023  Italia



Proprietarul s-a schimbat

Țara (sau statul) a indicat locația geografică a unei schimbări sau reînnoiri documentate de proprietar. Vă rugăm să rețineți că unele modificări pot fi formale, de exemplu, transferurile de la sfârșitul contractului de leasing sau situații similare.



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**