



Seat terramar

VIN: VSSZZZKP8S1021444 Diesel 2025



Generat pe 06.06.2025

Scanează ca să accesezi raportul complet

Kilometri parcurși

✓ Arată bine

Statut legal

✓ Arată bine

Daune

✓ Arată bine

+36 Surse de date
Am verificat 900+ de surse de date în 40 de țări

Furt

Vehiculul este declarat furat în prezent? A fost furat în trecut? A fost recuperat?

✓

Nu s-au găsit probleme
Nu am găsit nicio înregistrare că vehiculul a fost furat.

i

Notă
Am încheiat verificarea bazelor de date ale poliției privind vehiculele furate din 10 țări: +4

Iată ce am verificat:

Căutat drept furat

✓ Nu s-a găsit nicio înregistrare

Furat în trecut

✓ Nu s-a găsit nicio înregistrare

 Nu au fost găsite înregistrări anterioare de furt pentru acest vehicul.

Bazele de date ale poliției cu vehicule furate **verificare finalizată în:**

- România Lituania Italia Slovenia Cehia Ungaria Slovacia Suedia Statele Unite ale Americii
- Canada


Kilometri parcurși

Există semne conform cărora kilometrajul a fost dat înapoi sau sunt discrepanțe de kilometraj?

i

Notă

- Ultimul kilometraj cunoscut: 18 km
- 1 înregistrare a kilometrajului



2025

Înregistrările odometrului

01.2025

18 km

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost marcat drept casat?



Nu s-au găsit probleme

Nu s-au găsit înregistrări despre statutul legal al acestui vehicul

Legal



Inspecție tehnică periodică (ITP)



Nu s-a găsit nicio înregistrare

Nu au fost găsite înregistrări ale inspecției tehnice



Casat



Nu s-a găsit nicio înregistrare

Nu există nicio înregistrare că vehiculul a fost marcat drept casat

Daune

Această secțiune te ajută să înțelegi dacă vehiculul a fost avariat sau inspectat pentru daune și prezintă estimările înregistrate ale costurilor (dacă sunt disponibile).



Nu s-au găsit probleme

Înregistrări de daune



Ocazional pot apărea inexactități, mai ales la verificarea vehiculelor vechi. Atelierele clandestine de reparații pot deghiza ilegal defectele sau daunele vehiculelor, fără să declare nicăieri existența lor. Uneori până și plăcuțele VIN ale vehiculului pot fi înlocuite. Avem o varietate de metode de a detecta chiar și astfel de infracțiuni, dar este imposibil de oferit o garanție de 100%.

Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?



Nu s-au găsit probleme

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Emisii

Care este nivelul de emisii de CO₂ al vehiculele din acest model/an?



Sugestia carVertical

Acest vehicul are emisii ridicate. Acest lucru poate să însemne că vor fi aplicate taxe mai ridicate pentru emisii. Verifică reglementările locale ca să eviți surprizele neplăcute.

Emisii CO₂

Emisii CO₂ g/km

Până la
120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 +

vehiculului
tău

195 g/km

Clasă **F**

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?



Notă

Verifică dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător

Seat

Model

terramar

Tip caroserie

Hatchback

An de fabricație

2025

An model

2025

Capacitate cilindrică

1,5 l

Putere motor

195 kW (261 cp)

Tip combustibil

Diesel

Cutie de viteze

Automată

Tip transmisie

Tracțiune integrală (AWD)

Culoare

Alb



Amplasarea volanului

Volan pe stânga



Nr. locuri

5



Cod motor

DNPB



Categorie

m1

Echipare

Cum a fost primit de la producător

05Z

WITHOUT SPECIAL SPECIFICATIONS

0B3

WHEELBASE

0FA

STANDARD MANUFACTURING SEQUENCE

0K0

WITHOUT ALTERNATIVE DRIVE SYSTEM

0TA

WITHOUT FLOOR MATS

0Y1

STANDARD CLIMATIC ZONES

1A5

FUEL SYSTEM FOR SI ENGINE

1E5

ACTIVATED CARBON CANISTER FOR INTENSIFIED
EVAPORATION SYSTEM WITH ON-BOARD
DIAGNOSTIC SYSTEM 2

1G9

SPACE-SAVING SPARE WHEEL FOR TEMPORARY USE,
RADIAL TIRE (5-HOLE)

1JP

0AL

FRONT STABILIZER

0BG

REAR STABILIZER

0IJ

INSTALLATION DIFFERENTIATION FOR TRANSMISSION
"DQ381" -- VEHICLE COMPONENTS --

0NA

WITHOUT NAMEPLATE SET (WITHOUT MODEL
DESIGNATION)

0XH

INFORMATION KIT IN ROMANIAN

0YF

WEIGHT RANGE 6 INSTALLATION CONTROL ONLY, NO
REQUIREMENT FORECAST

1AQ

BRS FOR VEHICLES WITHOUT ELECTRIC DRIVE (ESC
AND ELECTRIC BRAKE BOOSTER)

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1
PASSENGER VEHICLE

1J2

SOUND DEADENING PACKAGE AND ADDITIONAL
ENCLOSURES FOR SOME UNITS

1KY

REAR SHOCK ABSORPTION

1N7

DYNAMIC STEERING

1PE

WHEEL BOLTS WITH ANTI-THEFT PROTECTION (UNLOCKABLE)

1S1

TOOL KIT AND JACK

1T0

WITHOUT FIRST AID KIT AND WARNING TRIANGLE

1X1

FOUR WHEEL DRIVE

1ZN

DISK BRAKES IN FRONT (GEOMET D)

2F0

WITHOUT LOCKING AND STARTING SYSTEMS

2PT

LEATHER-WRAPPED STEERING WHEEL FOR AIRBAG SYSTEM WITH ADDITIONAL MASS

2Z3

TYPE SIGN AND COMPANY LOGO

3C7

3-POINT SEAT BELT FOR CENTER REAR SEAT

3FU

BIG ROOF SYSTEM

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3L4

POWER SEAT ADJUSTMENT FOR BOTH FRONT SEATS, DRIVER SEAT WITH MEMORY FEATURE

3Q6

THREE REAR HEAD RESTRAINTS

3U1

FOLDING TRUNK COVER

4A3

DISK BRAKES IN REAR

1NL

TRIMS FOR ALLOY WHEELS

1Q0

WITHOUT MASS DAMPER FOR STEERING WHEEL

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1U8

WITHOUT FOLDING TABLE ON FRONT SEAT BACKREST

1Z0

INITIAL STANDARD FUEL FILLING

2A0

WITHOUT DELIVERY EQUIPMENT

2JK

SPORTS BUMPERS

2WA

WITHOUT ADDITIONAL TIRES

31A

WITHOUT LICENSE PLATE CARRIER

3CA

WITHOUT PARTITION

3GN

VARIABLE CARGO AREA

3J9

HEAD RESTRAINT FOR FRONT SEAT

3LM

DOOR AND SIDE TRIM PANEL

3S5

BLACK ROOF RAILS

3ZU

3-POINT SEAT BELTS, OUTER REAR WITH ECE LABEL

4D0

WITHOUT SEAT VENTILATION/MASSAGE SEAT

SEAT HEATER FOR FRONT SEATS SEPARATELY
CONTROLLED

4E6

SENSOR-CONTROLLED LUGGAGE COMPARTMENT
OPENER

4GQ

WINDSHIELD IN HEAT-INSULATING GLASS

4L6

BREAKAWAY INTERIOR REARVIEW MIRROR, AUTO-
DIMMING

4QU

3-POINT SEAT BELTS IN FRONT, WITH TENSIONER
AND ELECTRIC HEIGHT ADJUSTMENT

4U0

WITHOUT LUGGAGE NETS/POCKETS ON BACKRESTS

4VN

ONE 3-POINT SEAT BELT AND ONE LAP BELT WITH
RETRACTOR IN 3RD ROW OF SEATS

5A5

LUGGAGE COMPARTMENT LINING, WITH
STORAGECOMPARTMENTS

5F1

1 ARMREST FOR LEFT FRONT SEAT AND 2 ARMRESTS
FOR RIGHT FRONT SEAT

5K7

TRANSPORT PROTECTION FILM (MINIMUM
PROTECTION) WITH ADDITIONAL TRANSPORT
PROTECTION MEASURES

5N4

FOLDING GRAB HANDLES, MULTI-PIECE

6A0

WITHOUT FIRE EXTINGUISHER

6E3

CENTER ARMREST IN FRONT

6F3

4G3

STORAGE COMPARTMENT, LEFT AND RIGHT 1ST ROW
OF SEATS

4K6

CENTRAL LOCKING SYSTEM "KEYLESS ENTRY" WITH
FINGERPRINT "TWO-STAGE UNLOCKING"

4N2

STANDARD DASHBOARD

4R4

POWER WINDOWS WITH COMFORT OPERATION
ANDCIRCUIT BREAKER

4UF

DRIVER AND FRONT PASSENGER AIRBAG WITH
FRONT PASSENGER AIRBAG DEACTIVATION

4ZE

BLACK MOLDINGS

5C0

WITHOUT SPECIAL BODY MEASURES

5JB

AMBULANCE SEAT FOR MEDICAL STAFF WITH HEAD
BOLSTER ON PARTITION

5KR

REAR SEAT BENCH/BACKREST, SPLIT FOLDING

5XJ

SUN VISORS WITH MIRROR, ILLUMINATED, WITH
AIRBAG LABEL ON SUN VISOR AND B-PILLAR

6C2

SIDE AIRBAG IN FRONT WITH CURTAIN AIRBAGAND
INTERACTION AIRBAG IN FRONT

6EA

WITHOUT ADDITIONAL SIDE BODY COVERS (STONE
GUARD)

6FF

EMBLEMS

6I6

LANE KEEPING SYSTEM PLUS SEMI-AUTOMATIC
VEHICLE CONTROL IN A MEDICAL EMERGENCY AND
TRAFFIC JAM ASSIST

6T1

INTERIOR LIGHT IN FOOTWELL

76A

WITHOUT MODE 3 CHARGING CABLE

7B3

12-VOLT SOCKET(S)

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7P1

POWER-ADJUSTABLE LUMBAR SUPPORT IN
FRONTSEATS

8DG

RADIO "RNS 4010"

8GV

ALTERNATOR 180 A

8J3

HAND BRAKE/LOW BRAKE FLUID LEVEL
WARNINGLIGHT AND INSCRIPTION

8N6

WINDSHIELD WIPER INTERMITTENT CONTROL WITH
LIGHT/RAIN SENSOR

8S4

TWO READING LIGHTS IN FRONT, TWO IN REAR

8WH

FRONT FOG LAMP AND CORNERING LAMP

8Y1

TWO-TONE HORN

8ZQ

ANTENNA FOR FM RECEPTION ONLY, DIVERSITY

BODY-COLORED EXTERIOR MIRROR HOUSINGS AND
VARIOUS ADD-ON PARTS

6NL

UNSPLIT MOLDED HEADLINER

6XQ

EXTERIOR MIRRORS: WITH MEMORY FEATURE,
POWER-FOLDING/ADJUSTABLE, SEPARATELY HEATED

7AL

ANTI-THEFT ALARM SYSTEM, INTERIOR MONITORING,
BACKUP HORN, AND TOWING PROTECTION

7E0

WITHOUT HEAT ACCUMULATOR/AUXILIARY HEATER

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

8A2

INTELLIGENT PARK ASSIST IPA

8FA

WITHOUT SECOND BATTERY

8IV

LED HEADLAMPS WITH VARIABLE LIGHT
DISTRIBUTION

8M1

REAR WINDOW WIPER AND WASHER SYSTEM WITH
INTERMITTENT CONTROL

8Q3

AUTOMATIC HEADLIGHT RANGE ADJUSTMENT
DYNAMIC (SELF-ADJUSTING WHILE DRIVING)

8T3

ADAPTIVE CRUISE CONTROL

8X7

WITHOUT HEADLAMP WASHER SYSTEM / WITH
WASHER FLUID LEVEL INDICATOR

8Z5

NOT HOT COUNTRY

9I5

9JA

NON-SMOKER'S PACKAGE

9P4

SEAT BELT REMINDER, ELECTRIC CONTACT IN FRONT AND REAR, VISUAL AND ACOUSTICAL

9T0

WITHOUT HEATED WASHER NOZZLES

9WJ

POWER SUPPLY/TV SIGNAL FOR CUSTOMIZED INSTALLATION

9ZP

CAR PHONE INSTALLATION (PERMANENT INSTALLATION)

A8I

SPORTS EQUIPMENT

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

C01

OPERATING PERMIT, ALTERATION

E0A

NO SPECIAL EDITION

EL5

ONLINE SERVICE, WITH OCU, WITH HEAD UNITCODING, WITHOUT ENGINE IMMOBILIZER INTERCONNECTION

EV0

WITHOUT CHARGING CABLE

F09

ALLOY WHEELS 8.5J X 19

FA0

CONTROL OF SERIES PRODUCTION

FC0

SEPARATE DAYTIME RUNNING LIGHTS WITH AUTOMATIC HEADLAMP ACTIVATION AND COMING HOME FEATURE (AUTOMATIC)

9M9

FUEL-FIRED PARKING HEATER WITH RADIO REMOTE CONTROL

9S1

MULTI-FUNCTION DISPLAY/ON-BOARD COMPUTER

9VN

DIGITAL SOUND PACKAGE

9Z3

12-V OPERATING VOLTAGE AND 230-V INVERTER

A23

IN-PLANT CONTROL OF SELF-COLLECTION

AV1

DRIVING ON THE RIGHT

B43

TYPE APPROVAL COUNTRY ROMANIA

D3Q

4-CYLINDER SI ENGINE 2.0 L/195 KW (16 V)TURBO FSI, HOMOGENEOUS BASE ENGINE IS TA2/TT6

EA0

WITHOUT FOLLOW-ON WARRANTY

ER1

REGIONAL CODE " ECE " FOR RADIO

EW0

WITHOUT MAINTENANCE CONTRACT

FOA

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FB0

STANDARD PAINT COATING

FM0

WITHOUT CUSTOMIZED INSTALLATION

G03

SHOCK ABSORPTION IN FRONT

GB1

BOOSTER TYPE 1

GP0

VEHICLES WITHOUT SPECIAL UPGRADE MEASURES

GW2

CAR2X "HIGH" VARIANT

IM0

FRONT AXLE WEIGHT, STANDARD

J2D

BATTERY 380 A (68 AH)

K8G

HATCHBACK

KH7

CLIMATRONIC (3-ZONE) WITH REAR AIR
CONDITIONING CONTROL PANEL

KS0

WITHOUT HEAD-UP DISPLAY

L36

SUSPENSION RANGE 36 INSTALLATION CONTROL
ONLY, NO REQUIREMENT FORECAST

NY0

STANDARD BATTERY/ALTERNATOR CAPACITY

Q1D

SPORTS SEATS IN FRONT

QH1

VOICE CONTROL

QJ3

CHROME PACKAGE (TYPE 2)

QL5

DARK TINTED GLASS IN REAR SEAT AREA (VENUS
35/PRIVACY) HEAT-INSULATING GLASS (GREEN) IN

BASIC EQUIPMENT VARIANT

G1D

7-SPEED AUTOMATIC TRANSMISSION FOR FOUR-
WHEEL DRIVE

GM1

STANDARD ELECTRONIC ENGINE SOUND

GV1

SWITCH IN GEARSHIFT LEVER FOR REAR-AXLE
DIFFERENTIAL LOCK

H2Y

TIRES 225/35 R18 87Y XL

IN0

REAR AXLE WEIGHT, STANDARD

JX1

WITH FRONT CROSS TRAFFIC ASSIST

KA6

WITH FRONT AND REAR VIEW CAMERA SYSTEM AND
TWO SIDE CAMERAS

KK3

REFRIGERANT R1234YF

L0L

LEFT-HAND DRIVE

N0F

SEAT TRIM COVERS IN WOVEN FABRIC

NZ4

PRIVATE EMERGENCY CALL SYSTEM

QG1

SERVICE INTERVAL PROLONGATION

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS (
VARIABLE)

QK1

WITH MULTIFUNCTION CAMERA

QN0

WITHOUT DRAWERS UNDER FRONT SEATS

FRONT

QQ8

INTERIOR AMBIENT LIGHTING, TYPE 1

QV3

DIGITAL RADIO RECEPTION

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

UH2

PARKING BRAKE

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

VF1

PEDAL CLUSTER

VT2

SCUFF PLATES IN DOOR APERTURES (ILLUMINATED)

X4N

EQUIPMENT OPTIONS SUBSET FOR ROMANIA

QR9

WITH DYNAMIC ROAD SIGN DISPLAY

T3J

3-CYLINDER DIESEL ENGINE 1.5 L UNIT 05M.A

U9E

4 X USB TYPE C

UK1

STANDARD REAR SEAT RELEASE

VC0

WITHOUT REMOTE-CONTROLLED GARAGE DOOR OPENER

VL1

EXTENDED PEDESTRIAN PROTECTION MEASURES

VW5

SIDE AND REAR WINDOWS

Cronologie

S-au găsit 4 înregistrări

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

01.2025 🌐 Țară necunoscută

 A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

02.2025 🇷🇴 România

 Prima înmatriculare

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

05.2025  România



A fost asigurat

Acest vehicul a fost asigurat în această țară (sau stat). Pot fi acoperite toate tipurile de asigurare (răspundere civilă față de terți, CASCO etc.), precum și reînnoirea polițelor.

Din: 06.05.2025

Până la: 05.11.2025

06.2025  România



A fost asigurat

Acest vehicul a fost asigurat în această țară (sau stat). Pot fi acoperite toate tipurile de asigurare (răspundere civilă față de terți, CASCO etc.), precum și reînnoirea polițelor.

Din: 03.06.2025

Până la: 02.09.2025



+36

Surse de date

Am verificat 900+ de surse de date în **40 de țări**