
CARVERTICAL




Purpose

Was the vehicle used as a taxi, rental, or other service vehicle? Note: such vehicles may be in worse condition than usual!

0	No issues found No records of vehicle being used in irregular manner			
Here's what we checked:				
т 🏡	Taxi V No record found No evidence of being used as a taxi			
י 🕼	ransport Vo record found No evidence of being used as a transport vehicle			
R€ SR ₽	Rental Vorecord found No evidence of being used as a rental vehicle			
€ B F	Police Vorecord found No evidence of being used by police			
e 1	Demo V No record found No evidence of being used as a demo vehicle			
<u>ې</u>	Driving school vehicle 🗸 No record found No evidence of being used as a driving school vehicle			
Theft				

Is the vehicle currently marked as stolen? Was it stolen in the past? Has it been recovered?




Are there signs of mileage rollbacks or discrepancies?

CARVERTICAL

Note

- Last known mileage: 21,000 km
- Average mileage for similar models: 22,762 km
- 2 mileage records found



Legal status

Has the vehicle passed technical inspection? Was it marked as scrapped?

No issues found No records about the legal status of this vehicle were found Legal ✓= Technical inspection (MOT) ✓ No record found No technical inspection records found ✓ ✓ Scrap ✓ No record found No record that vehicle was marked as scrapped

Damage

This section helps you understand whether the vehicle was damaged or inspected for damage, along with recorded cost estimates (if available).


CARVERTICAL

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Note

Mild damages normally won't impact a vehicle's safety or leave structural issues

Damage records



We grouped these damage assessment records together in this PDF report – they appear to describe the same event, as they share consistently similar dates, locations, and details. To view all available details and ensure you're seeing the most detailed and up-to-date information, please refer to the digital report on our website.

Disclaimer: Most damage entries are related to traffic accidents, but not exclusively. Some entries may end up on the report for different reasons, such as damage assessments, auctions, vehicle inspections, repairs and other similar events, actions or circumstances. Entries like these may indicate, for example, that the vehicle was inspected and assessed at an authorised service centre, or that repairs, warranty service, diagnostics, vehicle inspection or other similar services were performed. These vehicle inspections or assessments may be done due to damage caused during a traffic accident, but also for other reasons, such as legal requirements and/or processes, information published by the manufacturer, warranty or non-warranty repairs, correction of poorly performed repairs, or damage not related to traffic accidents (e.g. theft, mechanical damage, etc.). It is important to note that such entries do not necessarily indicate the consequences of a traffic accident – they may also be related to the use, maintenance or operation of the vehicle in accordance with the requirements and circumstances set by the manufacturer or third parties.

Damage Glossary

Assessment

Assessment is the process of evaluating the extent of damage to a vehicle. It involves inspecting the vehicle to determine what repairs are needed, estimating the costs, and deciding whether the vehicle is repairable or considered a total loss.

Estimated Repair Cost

Once an incident related to a vehicle is assessed, damage data providers calculate the repair cost and present it in the currency of the country where the damage was evaluated. Therefore, this may not align with your expectations. The reasons for this may include:

The country or state where damage to the vehicle was assessed may have higher/lower servicing costs compared to your country (spare part prices and labor prices differ between countries)

The cost is calculated for repairs at an official service station (which is typically on the expensive end)

Natural disasters

Has the vehicle's location been recorded in the area of a natural disaster?



No issues found

Vehicle's location was not recorded in the area of a natural disaster

CARVERTICAL

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Market value

How much was the vehicle sold for in the past? What is the price of vehicles of this year and model on average?

Note

- Average market price for such vehicle: €90,828
- Be cautious of hidden issues if the vehicle was on sale for significantly less than the current price!

BMW M4 2022 market value today

Market value is determined by examining the price of a particular car model (manufactured in the same year) in the country where the report was generated. We analyze data from the last 6 months.



Specs & equipment

What specs and equipment are on record for this vehicle?



Check whether the specs and equipment of this vehicle match the facts given by the seller.

Identification and technical specifications

A	Make BMW
4	Model M4
	Description m4 competition m xdrive
Ą	Variant 4' G82 M4 Coupé
4	Body type Coupe
	Manufacture year 2022
77 77	Powertrain displacement 3 L
4	Powertrain power 375 kW (503 hp)
0 <u>-0</u> 0-0	Torque 650 Nm
믿)	Fuel type Gasoline

CARVERTICAL

æ	Transmission type Automatic
0+0 0+0	Drive type AWD
Ŋ	Color Black
6	Steering wheel placement LHD
77	Number of cylinders 6

Equipment

As received from the manufacturer

1CB

CO2 CONTENT

1MB

M DRIVE PROFESSIONAL

2PA

LOCKING WHEEL BOLTS

2VB

TYRE PRESSURE INDICATOR

302

ALARM SYSTEM

3MF

BMW INDIVIDUAL SHADOWLINE LIGHTS

428

WARNING TRIANGLE

431

INTERIOR REAR-VIEW MIRROR WITH AUTOMATIC ANTI-DAZZLE FUNCTION

488

LUMBAR SUPPORT DRIVER/FRONT PASSENGER

494

SEAT HEATING FOR DRIVER AND FRONT PASSENGER

4NE

BLOW-BY HEATER

534

AUTOMATIC AIR CONDITIONING

548

SPEEDOMETER WITH KILOMETER READING

5AV

ACTIVE GUARD

1DF

EXHAUST EMISSIONS STANDARD EU6D

230

EU-SPECIFIC ADDITIONAL CONTENTS

2T4 M SPORT DIFFERENTIAL

2VF ADAPTIV M SUSPENSION

3M5 M COMPOUND BRAKE WITH RED CALIPERS

420 SUN PROTECTION GLAZING

430 INTERIOR AND EXTERIOR MIRROR PACKAGE

459 SEAT ADJUSTMENT, ELECTRIC, WITH MEMORY

493

STORAGE COMPARTMENT PACKAGE

4MC INTERIOR TRIM FINISHERS CARBON FIBRE

400 GALVANIC EMBELLISHER FOR CONTROLS

VIN: WBS41AZ020CK75951

DYNAMIC CRUISE CONTROL

5AC AUTOM. HIGH-BEAM HEADLIGHTS CONTROL

5AZ

544

BMW LASER LIGHT

CARVERTICAL

5DA

FRONT PASSENGER AIRBAG DEACTIVATION

654

DAB TUNER

6AE

TELESERVICES

6AK

CONNECTEDDRIVE SERVICES

6NW

TELEPHONY WITH WIRELESS CHARGING

6U3

BMW LIVE COCKPIT PROFESSIONAL

6WD

WIFI HOTSPOT

760

INDIVIDUAL HIGH-GLOSS SATIN CHROME

7M9

BMW INDIVIDUAL HIGH-GLOSS SHADOWLINE EXTERIOR TRIM WITH EXTENDED FEATURES

851

LANGUAGE VERSION GERMAN

8EK

BODY CONTROL

8R9 REFRIGERANT


Timeline

2 records found

The timeline of records for this vehicle

Records

05/2022 🚯 Country unknown



The country (or state) indicates either the location of the manufacturing facility, assembly plant, or registration address of the manufacturer. The date may be approximate.

04/2023 **— Germany**



We have indications that this vehicle underwent an assessment in this country (or state). Please refer to the "Damage" section for detailed information.



Data sources We checked 900+ data sources in 40 countries

CARVERTICAL



PARKING ASSISTANT

688

HARMAN/KARDON SURROUND SOUND SYSTEM

6AF

LEGAL EMERGENCY CALL

6C4 CONNECTEDPACKAGE PROFESSIONAL



WI-FI FUNCTIONS, TEMPORARY DELETION & AMP; PREPARATION FOR REMOTE SOFTWARE UPGRADE

6UX

BMW CONTROLLER WITHOUT TOUCH-FUNCTION

712 **M SPORTS SEAT**

775

INDIVIDUAL ROOF-LINING ANTHRACITE

801

GERMAN VERSION

879

GERMAN / ON-BOARD DOCUMENTATION

8KA OIL SERVICE INTERVAL - 24 MONTHS/30,000 KM



ACTIVE PEDESTRIANS SAFETY

VIN: WBS41AZ020CK75951 This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.