

Car History Report

Report ID:	5799889422
Data achiziției raportului:	27. 02. 2026 16:23:58
Valabil până la:	29. 03. 2026 23:59:59

1. Datele de bază ale vehiculului



VIN
VSSZZZKP1S1053149

✓ cifra de verificare este în regulă

Marca
CUPRA

Model
TERRAMAR

Tipul caroseriei
break

Tipul vehiculului
passenger

Combustibil
benzină

Data fabricației
06/2025

2. Verificare kilometraj

Prezentarea generală a unei evoluții a contorului de parcurs al vehiculului conține valori obținute din sistemele de informații disponibile ale partenerilor cooperanți. Conform dezvoltării graficului, puteți judeca singur dacă există o suspiciune de manipulare a stării contorului de parcurs sau nu.

Recomandare:

Este posibil să nu fie disponibile în sistem toate înregistrările privind starea contorului de parcurs din istoricul de funcționare al vehiculului.

Dacă vehiculul nu înregistrează în mod continuu întregul istoric al kilometrajului de-a lungul timpului, vă recomandăm să verificați și înregistrările contorului de parcurs din cartea de service sau să verificați vehiculul la un garaj autorizat. Recomandăm această procedură în special pentru vehiculele în care există o perioadă de timp mai mare de doi ani între citirile contorului de parcurs.



3. Prezentare generală a istoriei

	Data	Starea odometrului	Țara	Descriere
2025	06/2025	0 km		Vehicul fabricat
	Data fabricației: 06/2025 Vechimea vehiculului: 9 luni Culoarea mașinii: Cod 2D Fabricat pentru piața: România Postul de conducere: partea stângă			
	09/2025	10 km	 România	Datelor odometrului
	09/2025		 România	Înregistrare RAR
	11/2025		 România	Inspekția tehnică

4. Verificarea daunelor

Nu s-au găsit înregistrări cu privire la daune

Nu au fost găsite înregistrări cu privire la daune în bazele de date de vehicule avariate din peste 32 țări, numărând 200 de milioane de înregistrări de daune.

Avertisment: Este posibil ca informațiile despre toate daunele vehiculului să nu fie disponibile în sistem, unele daune să nu fie raportate companiilor de asigurări sau să nu fie disponibile ca parte a unei verificări online. Vă recomandăm prin urmare o inspecție atentă a vehiculului, în mod ideal cu ajutorul unui mecanic calificat sau la centrul de service la alegere. O astfel de inspecție poate dezvălui daune suplimentare sau poate exclude.

5. Controlul furturilor

Nu este înregistrat drept furat

în bazele de date disponibile actualmente

Informațiile furnizate au doar caracter informativ.

Informațiile despre furtul vehiculelor sunt preluate din bazele de date publice disponibile în diferite țări și sunt afișate în forma în care apar în aceste baze de date. Compania Cebia nu poate garanta completitudinea sau actualitatea acestor baze de date și nici nu garantează că ele conțin toate vehiculele care au fost într-adevăr furate.

Din acest motiv, Cebia nu își asumă nicio responsabilitate pentru eventualele daune rezultate în urma utilizării acestor informații. Dacă vehiculul provine dintr-o țară care nu este inclusă în listă, vă recomandăm să verificați proveniența acestuia printr-o altă metodă sau să solicitați garanții corespunzătoare de la vânzător.

Sursa	La zi: 27. 02. 2026
 Olanda – Poliție	NF – nu este înregistrat drept furat
 Cehia – Poliție	NF – nu este înregistrat drept furat
 Slovacia – Poliție	NF – nu este înregistrat drept furat
 Ungaria – Poliție	NF – nu este înregistrat drept furat
 România – Poliție	NF – nu este înregistrat drept furat
 Slovenia – Poliție	NF – nu este înregistrat drept furat
 Ucraina – Poliție	NF – nu este înregistrat drept furat
 Suedia – Baza de date a companiilor de asigurare	NF – nu este înregistrat drept furat
 Baze de date private*	NF – nu este înregistrat drept furat

* Baze de date private sunt baze de date neoficiale, accesibile liber pe internet, care permit de obicei oricărei persoane să introducă o înregistrare privind furtul unui vehicul. Acestea nu sunt baze de date oficiale ale poliției dintr-un anumit stat sau din mai multe state.

6. Verificare utilizare

Vehiculul nu a fost exploatat ca taxi în Republica Cehă

În bazele de date disponibile s-a constatat că vehiculul nu a fost și nu este folosit în prezent ca taxi.

7. Verificarea finanțării

Finanțarea nu a fost găsită

Rezultatul solicitării constă în verificarea dacă vehiculul nu este obiectul finanțării (sub formă de leasing sau credit), garanții și împrumut de la companiile enumerate. Datele provin din sistemele informatice ale companiilor individuale.

Țara	La zi: 27. 02. 2026
Cehia	NF – nu este înregistrat

8. Lista elementelor echipamentelor conform producătorului

Acestea sunt informații disponibile despre parametrii de bază, echipamentele standard și eventual suplimentare ale vehiculului din fabrică. Modificările vehiculului, cum ar fi schimbarea părții laterale a volanului, pot fi detectate prin verificarea echipamentului.

Identificarea vehiculului

Marca	Cupra
Numele modelului	Terramar
Denumirea modelului	Terram1.5eTSIT 5d110 DS9A7
Data fabricației	13.06.2025
Cod de culoare	2D
Codul culorii acoperișului	2D
Codul cutiei de viteze	WFN
Codul motorului	DXDB
Capacitate motor ccm	1498
Capacitatea motorului(l)	1,50
Performanță(kW)	110
ISO numele țării	Romania
Cutia de viteze	7-speed automatic transmission "A7"
Numărul de viteze	7
Transmisie	AUT
Cod de control	LHD
Tipul de vânzare	KP1BNZ

Lista elementelor echipamentului vehiculului

Altele	"FRONT ASSIST" – with warning and braking reaction to vehicles, pedestrians and cyclists
Altele	"SMART LINK" (wired and wireless connect)
Altele	"SUNSET" + front side acoustic windows
Altele	12-V outlet in center console in rear and in luggage compartment
Altele	230-V outlet in luggage compartment
Altele	3 spoke sport multi-function leather steering wheel with heating and with DSGpaddles
Altele	3-point seat belt for center rear seat
Altele	3-point seat belts in front, with pretensioner and electric height adjustment
Altele	3-point seat belts, outer rear with ECE label
Altele	4 alloy wheels "York" 8.5J x 20, Black, Volkswagen R
Altele	4-cylinder SI engine 1.5 I TSI, 110 kW
Altele	4-cylinder SI engine 1.5 I unit 05E.D
Altele	4-way lumbar support for the front seats
Altele	7-speed automatic transmission
Altele	A8
Altele	Activated carbon canister (Evaporative Emission Control System (EVAP))
Altele	Adaptive Cruise Control ACC stop & go

Altele	Advanced high-beam control Dynamic Light Assist
Altele	Alloy wheels "Aracaju" 7J x 17, Silver
Altele	Antenna for FM reception only, diversity
Altele	Anti-theft alarm system, interior monitoring, backup horn, and towing protection
Altele	Area View incl. rear view camera system
Altele	Automatic headlight control with LED separate daytime running light and entry and exit lighting
Altele	Basic equipment variant
Altele	Battery 380 A (59 Ah) EFB+
Altele	Belt-driven integrated starter alternator 48 V 110 – 250 A
Altele	Black decorative trims
Altele	Black roof rails
Altele	Brake control system for vehicles with electric drive (ESC and electromechanical brake booster)
Altele	Breakaway interior rearview mirror, auto-dimming
Altele	Car2X
Altele	Center armrest in front
Altele	Climatronic (3-zone) with air conditioning control panel in rear
Altele	Comfort sports equipment CUPRA Terramar
Altele	Control of series production
Altele	Crossover
Altele	CUPRA MATRIX LED ULTRA
Altele	DAB – Digital radio reception
Altele	Decorative inserts in aluminum "Wave" and "Piano Black"
Altele	Digital sound package
Altele	Disc brakes in front
Altele	Disc brakes in rear
Altele	Door and side trim panel
Altele	Driver alert system with driver monitoring
Altele	Driver seat with memory feature, incl. power-adjustable front seats
Altele	Driving on the right
Altele	Driving Profile Selection
Altele	Dynamic headlight range control (self-adjusting while driving)
Altele	Emblems
Altele	Emergency call service, 10-year contract duration as of initial delivery, condition: mob. phone network available
Altele	Emission standard, WLTP3 M1, N1-I//EU6EB
Altele	Equipment options subset for Romania
Altele	Extended pedestrian protection measures
Altele	Exterior mirror housings and various add-on parts in body color
Altele	Exterior mirrors with memory feature, power-folding/adjustable, separately heated
Altele	Exterior mirrors: convex on driver side, convex on front passenger side
Altele	External, USB type C data socket(s) and charging socket(s) with increased charging performance

Altele	Folding grab handles, multi-piece
Altele	FPK Display
Altele	Front axle weight, standard
Altele	Front Cross Traffic Assist
Altele	Front fog lamps and cornering light
Altele	front passenger airbag deactivation
Altele	Front seats with power adjustment
Altele	Front stabilizer bar
Altele	Front-wheel drive
Altele	Fuel system for fuel-injected SI engine
Altele	Head restraint for front seat
Altele	Head-up display
Altele	Hybrid drive system MHEV
Altele	Child seat anchors f. child seat system i-Size, 2x top tether and child seat anchors in front on front passenger side
Altele	Chrome trim on rotary light switch, hazard warning light switch, mirror adjustment switch, window lifter switch
Altele	Illuminated vanity mirrors in sun visors
Altele	Infotainment system with scalable module options (Optionsinfotainment, MIB3 model update) version 2
Altele	Initial standard fuel filling (6L)
Altele	In-plant control of self-collection
Altele	Installation differentiation for transmission DQ381 — vehicle components —
Altele	Instrument cluster, km/h speedometer
Altele	Interior ambient lighting, type 1
Altele	Keyless locking and starting system "Keyless Advanced" with SAFELOCK
Altele	Lane Assist with adaptive lane guidance function + Emergency Assist
Altele	Lane change system Side Assist, Rear Traffic Alert and exit warning system
Altele	Leather-wrapped steering wheel
Altele	LED headlamps with variable light distribution
Altele	LED light unit in front footwell
Altele	LED rear combination lamp, variable lighting functions
Altele	Left-hand drive
Altele	LongLife Service Regime
Altele	LTE support for Audi phone box
Altele	Luggage compartment cover, folding
Altele	Luggage compartment floor adjustable in 2 heights, for flat cargo area, with fixation element
Altele	Luggage compartment trim, with storage compartments
Altele	Manual in Romanian
Altele	Memory feature for Park Assist
Altele	Mobile phone interface "Comfort" with inductive charging feature, charging capacity up to 15 W
Altele	Navarra Blue Metallic/Navarra Blue Metallic
Altele	Navigation system

Altele	No special edition
Altele	No special purpose vehicle, standard equipment
Altele	Non-smoker's package
Altele	Not hot country
Altele	Operating permit, alteration
Altele	Panoramic glass roof
Altele	Park Assist Plus with Park Distance Control
Altele	Parking brake
Altele	Part set without country-specific prescriptive standard
Altele	Power tilting panoramic sunroof
Altele	Power windows with comfort operation and circuit breaker
Altele	Predictive speed limiter
Altele	Preparation for alcohol interlock
Altele	Preparation for VW Connect and VW Connect Plus
Altele	Proactive passenger protection system
Altele	Progressive steering
Altele	Rear axle weight, type 2
Altele	Rear fog light on one side, back-up light on both sides
Altele	Rear seat bench plus with center armrest and cup holder
Altele	Rear stabilizer bar
Altele	Rear window wiper and washer system with intermittent control
Altele	Refrigerant R1234yf
Altele	Regional code " ECE " for radio
Altele	Remote Access / Remote Access + Online Infotainment
Altele	Scuff plates in door apertures (illuminated)
Altele	SE rim package for USA
Altele	Seat heater for front seats separately controlled
Altele	Seat trim covers in woven fabric
Altele	Service indicator 30 000 km or 2 years (variable)
Altele	Shock absorption in front
Altele	Side airbag in front with curtain airbag and interaction airbag in front
Altele	Space-saving spare wheel for temporary use, radial tire (5-hole)
Altele	Special identification label for EC for M1 passenger vehicles
Altele	Special price
Altele	Sport seats, front
Altele	Sport suspension
Altele	Sports bumpers
Altele	Stainless steel pedals
Altele	Standard battery/alternator capacity
Altele	Standard climatic zones

Altele	Standard electronic engine sound
Altele	Standard manufacturing sequence
Altele	Standard paint coating
Altele	Standard rear seat release
Altele	Start-stop system with regenerative braking
Altele	Sun protection glass, tinted
Altele	Suspension range 34 installation control only, no requirement forecast
Altele	Three rear head restraints
Altele	Tilting and sliding panoramic sunroof with rear panoramic sunroof
Altele	Tire pressure monitoring system
Altele	Tires 255/40 R20 101V XL
Altele	Tires without specification of tire brand
Altele	Tool kit and jack
Altele	Total business for Ambition
Altele	Transport protection film (minimum protection) with additional transport protection measures
Altele	Tray with cover on dashboard
Altele	Trims for alloy wheels
Altele	Two reading lights in front, two in rear
Altele	Two-tone horn
Altele	Type approval country Romania
Altele	Type sign and company logo
Altele	Unsplit molded headliner
Altele	UWB-capable country and carrier frequency, 433.92 to 434.42 MHz
Altele	Vehicle class differentiation -57S-
Altele	Virtual pedal
Altele	Visual and acoustic seat belt reminder, electric contact in front and rear
Altele	Voice control
Altele	Weight range 5 installation control only, no requirement forecast
Altele	Wheel locks with extended theft protection
Altele	Wheelbase
Altele	Windshield in heat-insulating glass
Altele	Windshield wiper intermittent control with light/rain sensor
Altele	With dynamic road sign display
Altele	With emergency steering support with turn assist
Altele	With multifunction camera
Altele	With UN-ECE cybersecurity & software update
Altele	With welcome light (mirror)
Altele	Without additional front underbody guard
Altele	Without additional side body covers (stone guard)
Altele	Without additional tires

Altele	Without auxiliary heater/parking heater
Altele	Without backrest release for front seats
Altele	Without customized installation
Altele	Without delivery equipment
Altele	Without drawers under front seats
Altele	Without exterior ambient lighting
Altele	Without fire extinguisher
Altele	Without first aid kit and warning triangle
Altele	Without floor mats
Altele	Without folding table on front seat backrest
Altele	Without garage door opener
Altele	Without headlamp washer system, with washer fluid level indicator
Altele	Without heat accumulator/auxiliary heater
Altele	Without heated washer nozzles
Altele	Without charging cable
Altele	Without license plate carrier
Altele	Without locking and starting systems
Altele	Without luggage nets/pockets on backrests
Altele	Without mass damper for steering wheel
Altele	Without mode 3 charging cable
Altele	Without nameplate set (without model designation)
Altele	Without partition
Altele	Without seat ventilation/massage seat
Altele	Without second battery
Altele	Without special body measures
Altele	Without special specifications
Altele	Without trailer hitch

Avertisment: în unele cazuri, este posibil ca echipamentul complet al vehiculului să nu fie disponibil în sistem.

9. Notificări de rechemare

Nu au fost găsite notificări de rechemare care

vizează mașina inspectată

Notificările de rechemare se anunță de către producătorul vehiculului în mod obligatoriu prin lege în cazul în care vehiculul prezintă un defect de fabricație care pune în pericol sănătatea, siguranța sau mediul înconjurător. În cadrul notificării de rechemare, defecțiunea din serviciul autorizat este remediată gratuit. Datele sunt furnizate de portalul [Car-recalls.eu](https://car-recalls.eu) cu ajutorul sistemului RAPEX.

10. Verificarea culorii vehiculului

Verificați dacă culoarea actuală a vehiculului se potrivește cu culoarea declarată de producător. Dacă culoarea este diferită, vehiculul poate fi revopsit, dar și prăbușit sau furat.

Culoarea mașinii	
Culoarea conform producătorului vehiculului	Cod 2D

11. Verificarea securității vehiculului

Rezultatul inspecției constă în informații dacă vehiculul inspectat este securizat sub forma marcajelor pe sticlă și înregistrat în Sistemul OCIS. Dacă da, vă vom informa în privința codului marcat și a datei de înregistrare.

Informații despre efectuarea marcajului geamurilor	27. 02. 2026
Marcajul geamurilor	NU

12. Fotografii și anunțuri publicitare

Nu a fost găsită nicio înregistrare în legătură cu publicarea anunțurilor despre vehicule.

Această listă este supusă Termenilor și condițiilor generale aplicabile pentru verificările istoricului vehiculului. Înregistrările istoricului vehiculului pot să nu fie complete și erorile din partea furnizorilor de date nu pot fi excluse. Toate informațiile furnizate au doar scop informativ și, prin urmare, rezultatul inspecției vehiculului nu este garantat. Pentru o inspecție completă a vehiculului uzat, vă recomandăm o inspecție fizică atentă și un test drive.